



MAJOR PROBLEMS WITH ROOF
 FLASHING HEIGHTS (6 1/2" TOO LOW)
 WAY BELOW
 STANDARDS AT BEAMS
 ON BOTH SIDES
 SUGGEST GOING TO 8 1/2" + 6 1/2" = 15" SECTION
 (Proposed) + (Missing Inches)